



## SERVICE BULLETIN

HEAD OFFICE

: SUBARU BLDG,

FUJI HEAVY INDUSTRIES LTD.

SHINJUKU, TOKYO, JAPAN

NO : FAS-065

DATE: February 7, 1972

1. SUBJECT : Modification of Main Landing Gear Assemblies.

2. AIRCRAFT AFFECTED: FA-200 Series Aircraft, Serial Nos. 2 thru 201.

3. PRIORITY : Essential.

4. REASON : In order to improve safety of the main landing gears.

(An instance was reported where the axle slipped off from the thermal fitted socket.)

from the thermal litted socket./

5. DESCRIPTION : Check the thermal fitted portion of the axle and socket for looseness, and then install a bolt for security.

6. ACCOMPLISHMENT : One time inspection should be accomplished immediately

upon receipt of this Service Bulletin, and modification accomplished no later than the next 50 hour inspection.

7. APPROVAL : JCAB Approval (NO-TOKYO-O4O) January 24, 1972.

8. PARTS REQUIRED : The following parts will be furnished free of charge to

owners of the affected aircraft.

PART NO.	PART NAME	QTY	s/N of applicable a/c	
an4-6a	BOLT	2	12 THRU 201	
AN4-5A	BOLT	2	2 THRU 11	,
NAS679A4W MS21042L4 or	NUT	2	2 THRU 201	
AN960-416L	WASHER	2	12 THRU 201	

8. PARTS REQUIRED : (cont.)

> PART NO. PART NAME QTYS/N OF APPLICABLE A/C 200-812186-003 SPECIAL WASHER 2 2 THRU 201 MS24665-360 COTTER PIN · 2 THRU 11 2 M\$24665-132 COTTER PIN 2 2 THRU 11

9. SPECIAL TOOL

: None required.

10. WEIGHT AND BALANCE : Negligible.

ll. REFERENCE

: Not applicable.

12. MANHOUR REQUIRED

: 1.0 manhour required for PART I, and 2.0 manhours

for PART II.

#### 13. DETAILED INSTRUCTION:

#### A. PART I (Applicable to S/Ns 12 thru 201)

#### 1. One Time Inspection:

- (1) Clean the end of socket bore, and check for evidence of axial movement of axle. (See figure 1, detail B.)
- (2) If axial movement more than 2 mm is evident in the above inspection, contact Fuji Heavy Industries Ltd. immediately.
- (3) If no movement is found, accomplish modification as follows:

#### 2. Modification:

- (1) Jack up main landing gear.
- (2) Drill 0.250 to 0.254 inch diameter hole in socket and axle assy as illustrated in figure 1.
- (3) Remove all burrs, then apply wet zinc chromate primer to hole surfaces.
- (4) Insert AN4-6 bolt into hole with 200-812186-003 special washer. Position special washer against axle inside with radius of washer mated to radius of axle.
- (5) Install AN960-416L washer, and tighten NAS679A4W\_or MS21042L4 nut.
- (6) Lower main landing gear.

FAS - 065

PAGE 2 OF 5


### B. PART II (Applicable to S/Ns 2 thru 11)

#### 1. One Time Inspection:

- (1) Clean the end of socket bore, and check for evidence of axial movement of axle. (See figure 2, detail B.)
- (2) If axial movement more than 2 mm is evident in the above inspection, contact Fuji Heavy Industries Ltd. immediately.
- (3) If no movement is found, accomplish modification as follows:

#### 2. Modification:


- (1) Jack up airframe and remove tire.
- (2) Remove piston and socket attaching bolt and lower end of torque link, and then remove socket and axle assy.
- (3) Drill 0.250 to 0.254 inch diameter hole in socket and axle assy as illustrated in figure 2.
- (4) Remove all burrs, then apply wet zinc chromate primer to hole surfaces.
- (5) Insert AN4-5A bolt into hole from piston side as illustrated.
- (6) Position 200-812186-003 special washer against axle inside with radius of washer mated to radius of axle, then tighten NAS679A4W or MS21042L4 nut.
- (7) Install socket and axle assy, and connect lower end of torque link, using new cotter pin MS24665-132.
- (8) Install tire and secure with new cotter pin MS24665-360.
- (9) Lower airframe and remove jack.



FAS - 065 FIGURE 1. MODIFICATION OF MAIN LANDING GEAR

(APPLICABLE TO S/Ns /2 THRU 201)

PAGE 4 OF 5



SECTION A-A

# FIGURE 2. MODIFICATION OF MAIN LANDING GEAR (APPLICABLE TO S/Ns 2 THRU 11)

FAS - 065