SERVICE NEWS

<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>		HHHHHHHHH.	HEAD OFFICE; EBISU SUBARU BLDG. SHIBUYA, TOKYO, JAPAN
NO.	200-053	DATE January ,14, 2021	(SUPERSEDES NO.)
REV.		DATE	(SUPERSEDES NO.)
		REASON	

SUBARU CORPORATION

Notices of FAA's AD and EASA's AD regarding engine problem

This service news is being issued to inform owners and operators that FAA's AD and EASA's AD have been published as follows for Lycoming engines (IO-360-B1B) used in FA-200-180.

(1) FAA AD No.2020-25-12 (published on December 11, 2020)(2) EASA AD No.US-2020-25-12 (published on December 14, 2020)

These documents refer to a problem in the crankshaft (Superior Air Parts, Inc. P/N SL36500-A31) of these engines and provide instructions to avoid the problem, which may cause engine problems or an engine halt in flight.

Please check these documents to determine if your engine is applicable.