

~~SCAS APPROVED~~

NO.	200-056	DATE	October 28, 2021	(SUPERSEDES NO.)
REV.		DATE		(SUPERSEDES NO.)
		REASON			

Notices of Lycoming Service Bulletin regarding Engine Problem

This service news is being issued to inform owners and operators that the following service bulletin has been published by Lycoming for their engines (O-320-D2A and IO-360-B1B) used in FA-200-160 and FA-200-180 (excluding 180AO) types of aircraft.

LYCOMING SERVICE BULLETIN No. 643 (published on September 16, 2021): Crankcase Nut Safety Wire Inspection

In some engines, the safety wire of nuts securing the crankcase was found missing at the factory shipment. This service bulletin was published to provide instructions to inspect engines that possibly may have the same problem.

Some of FA-200-160 and FA-200-180 (excluding 180AO) aircraft may be applicable. Please refer to the service bulletin for confirmation.