

SERVICE NEWS

FUJI HEAVY INDUSTRIES LTD.

HEAD OFFICE : SUBARU BLDG.
SHINJUKU, TOKYO, JAPAN

NO. 200-022 DATE August 10,2011

(SUPERSEDES NO.)

REV. DATE

(SUPERSEDES NO.)

REASON

MANUFACTURERS' INFORMATION ON FAULTY FUEL INJECTORS

This Service News is to inform FA-200 operators that the AD and SB's listed below have been issued concerning fuel injectors used on Lycoming engines (P/N IO-360-BIB or AEIO-360-BIB) installed on Model FA-200-180 aircraft.

- (1) FAAAD No. 2011-15-10 (August 1, 2011)
- (2) AVSter Fuel Systems, Inc. DOCUMENT No. AFS-SB6 Rev.2 (April 6, 2011)
- (3) LYCOMING SERVICE BULLETIN No. 596 (April 27, 2011)

These publications address defect of diaphragm (P/N AV2541801 or AV2541803 manufactured by AVSter Fuel Systems) which is a component of the fuel injector. Since defective diaphragms could fail in fatigue prematurely, resulting in loss of the engine power, the above publications provide instructions to prevent occurrence of the engine power loss.

Please check for your aircraft as FA-200-180 aircraft might be affected.