SERVICE BULLETIN

FUJI HEAVY INDUSTRIES LTD.

NO. FAS-002

DATE 8 April 1969.

1. SUBJECT :

Change of recommended engine idle speed.

2. AIRCRAFT AFFECTED:

All FA-200 series airplanes.

3. PRIORITY:

Optional.

4. DESCRIPTION:

Fuji recommend the engine idle speed of 650 ~ 750 rpm as mentioned in unofficial owner's manual. If you are using in your country FSD-1076 or FSD-1077 as Flight Manual, please amend the engine speed at idle check and ignition switch check in paragraph 2.3 and 2.5 to above-mentioned engine r.p.m.

5. APPROVAL:

Not applicable.

6. ACCOMPLISHMENT:

On any time.