

S E R V I C E B U L L E T I N

FUJI HEAVY INDUSTRIES, LTD.

NO. FAS-020

DATE March 25, 1970

1. SUBJECT : Establishment of drain hole.

2. AIRCRAFT AFFECTED : FA-200 Serial No. 1 through 85 airplanes.

3. PRIORITY : Desirable.

4. REASON : In order to prevent the water stay in the aircraft structure.

5. DESCRIPTION : Make drain holes on the wing tip pans (covers of aileron mass balance) and the fuselage tail cone.

6. ACCOMPLISHMENT : At any time.

7. APPROVAL : Not applicable.

8. PARTS REQUIRED : Nothing.

9. SPECIAL TOOLS : Nothing.

10. WEIGHT AND BALANCE : No change.


11. REFERENCE : Nothing.

12. MANPOWER : Little.

13. WORK PROCEDURE : Make holes on the skin and tips as illustrated.

Illustration of drain hole

Under surface of aft fuselage



Cover of aileron mass balance

