

S E R V I C E B U L L E T I N

Fuji Heavy Industries, Ltd.

NO. FAS-029

DATE May 8, 1970

1. SUBJECT : Replacement of Baffle by Engine rebuilding.
2. AIRCRAFT AFFECTED : FA-200 Serial No. 12 and Subsequent.
3. PRIORITY : As Necessary.
4. REASON : Impossible installation of R.H. Rear Engine Baffle when installing adjustable Oil pressure Relief Valve by LYCOMING SERVICE INSTRUCTION No. 1172.
5. DESCRIPTION : Replace R.H. Rear Engine Baffle with new part.
6. ACCOMPLISHMENT : When Adjustable Oil pressure Relief Valve is installed to the Engine.
7. APPROVAL : Not Applicable.
8. PARTS REQUIRED : The following parts will be submitted to the owners with fee.

	Model	Parts Number	Nomenclature	Q'ty
New parts	FA-200-160	200-914106-101	ENGINE BAFFLE	1
	FA-200-180	203-914206-101	ENGINE BAFFLE	1
Old parts	FA-200-160	200-914106-001	ENGINE BAFFLE	
	FA-200-180	203-914206-001	ENGINE BAFFLE	

9. SPECIAL TOOLS : No Required.
10. WEIGHT AND BALANCE : No change.
11. REFERENCE : LYCOMING SERVICE INSTRUCTION NO. 1172.
12. MANPOWER : No change.