

NO. FAS-007

Fuji Heavy Industries, LTD.

DATE 6 December, 1969.

1. SUBJECT : Adhesion of hose on the vent tube of the main fuel tanks.
2. AIRCRAFT AFFECTED : FA-200 Serial No. 56 through 75 airplanes.
3. PRIORITY : Essential.
4. REASON : To avoid the miss installation or miss adjustment of vent hose.
5. DESCRIPTION : Hose should be made to adhere to the vent tube. The work procedure is described in the No. 13 WORK PROCEDURE.
6. ACCOMPLISHMENT : At the next 100 hour inspection.
7. APPROVAL : JCAB Approval No. 310. 5 December, 1969.
8. PARTS REQUIRED : Adhesive EC-847 or equivalent parafuel adhesive.
9. SPECIAL TOOLS : Nothing.
10. WEIGHT AND BALANCE: No change.
11. REFERENCE : Nothing.
12. MANPOWER : 0.5 MH
13. WORK PROCEDURE :
  - (1) Remove the hose from the vent tube under the main fuel tanks.
  - (2) Make the inner surface of hose rough by the sand-paper.
  - (3) Make the tube and hose clean by the alcohol.
  - (4) Make the hose adhere to the tube by EC-847 or equivalent adhesive and fix it by the clamp.

Note: The cut end of hose should be directed forward.